

## VEHICLE INSPECTION REPORT

<b>VIN:</b> 1FMPU18L3WLB11111	<b>Series:</b> Eddie Bauer	<b>Engine Type:</b> Gas	<b>Trans. Type:</b> Automatic
<b>Year:</b> 1998	<b>Body Style:</b> Sport Utility	<b>Engine Liters:</b> 5.4	<b>Odometer:</b> 67215
<b>Make:</b> FORD	<b>Exterior Color:</b> Black	<b>Engine Cyl.:</b> 8 Cylinder	<b>Maintenance:</b>
<b>Model:</b> EXPEDITION	<b>Interior Color:</b> Beige	<b>Engine Induct:</b>	<b>License Plate:</b>
<b>Inspection Date:</b> 09/10/2003	<b>City:</b> Laguna Niguel	<b>State, Zip:</b> CA, 92677	

ACCESSORIES:					
Airbag, Driver	4 Whl Drv	Airbag, Passenger	Steering, Power	Windows, Power	Audio, CD Changer
Cruise Control	Seats, Heated	Luggage Rack	Door, Power Locks	Seat, Power Driver	Running Boards
Tow Package	Traction Control	Trip Computer	Seats, Leather	Steering Wheel, Tilt	Cab, Doors - 4
Air Cond, Dual Zone	Radio, AM/FM w/Cass	Glass, OEM Tinted	Door, Pwr Locks Rem.	Bmpr, R Step w/Hitch	Seat, Third Row
Tr. Case,4WD,Elect Shift	Wheels, Alloy OEM	Air Cond. Front only	Brakes, Anti-Lock 4 Whl	Security Alarm, OEM	

TIRES:	Pos.	Tread	Manufacturer		Dia.	Actual Size		Pos.	Tread	Manufacturer		Dia.	Actual Size	
	LF	7/32	Goodyear		16"	245/70R16		RF	5/32	Goodyear		16"	245/70R16	
	LR	6/32	Goodyear		16"	245/70R16		RR	5/32	Goodyear		16"	245/70R16	
	SP	6/32	Goodyear		16"	245/70R16								

**EXCEPTION/DAMAGE: AN EXCEPTION IS A CONDITION NOTED OUT OF THE ORDINARY**

Zone/Area/Qualifier	Type Description	Severity	Comments
<b>Exterior:</b>			
Left Rear Qtr Panel/Pickup Box	Previous Repair	Over 12 inches	
Left Rear Door	Previous Repair	Over 12 inches	
Left Rear Door	Mldg/Emb/Ws Damage	Over 1/2 up to 1 in.	
Left Front Fender	Scatched	Over 1 up to 1 1/2 in.	
Left Front Fender	Scuffed	Over 2 up to 3 in.	
Right Front Fender	Scatched	Over 1 1/2 up to 2 in.	
Right Front Fender	Scuffed	Over 2 up to 3 in.	
Right Rear Qtr Panel/Pickup Box	Previous Repair	Over 12 inches	
Right Front Door	Mldg/Emb/Ws Damage	Over 1/2 up to 1 in.	
Right Front Mirror-Sideview	Scuffed	Over 1/2 up to 1 in.	
Front Hood	Previous Repair	Over 12 inches	

<b>Interior:</b>		
Front Carpet	Stained/Soiled	Over 6 up to 8 in.

<b>Tire &amp; Wheels:</b>
No Exceptions Recorded

<b>Glass:</b>		
Front Windshield	Cracked, Glass	Over 1/8 up to 1/2 in.

<b>Test Drive:</b>	
Brakes perform with no noticeable defects	Engine performs with no noticeable defects
Recommend transmission be checked further by a certified technician	Instrument panel performs with no noticeable defects
Steering performs with no noticeable defects	

**Inspection Comments:**

POSSIBLE FRAME DAMAGE/ALIGNMENT ISSUES...STRANGE TREAD WEAR

The SGS Vehicle Inspection Report summarizes condition of vehicle as observed by the inspector at the time of inspection. Ordinary wear and tear and other external factors can change a vehicle's condition and SGS makes no representation about the condition of any vehicle on the date of purchase. The SGS inspection does not use computer or other mechanical diagnostic equipment and is not a substitute for an examination by a qualified mechanic at a properly equipped repair facility. SGS relies on the state registration found with the vehicle to identify the owner and verify the VIN, but does not verify the registration, check for liens against the vehicle or make any representation or warranty about the title of the vehicle. All inspections are subject to **Terms and Conditions**.

