

## VEHICLE INSPECTION REPORT - MOTORCYCLE

VIN:	1HD1GEL12WY111111	Series:	No Entry Made	Engine Type:	Gas	Transmission Type:	5 Speed Manual
Year:	1998	Body Style:	Cruiser	Engine Liters/cc:	1340.00	Odometer:	8987
Make:	Harley-Davidson	Exterior Color:	Black	Engine Cylinders:	2 Cylinder	Maintenance:	0
Model:	Dyna	Interior Color:	N/A	Engine Induction:		License Tag:	
Inspection Date:	03/23/2004	City:		State, Zip:			

## ACCESSORIES:

Wheels, Alloy	Axle Cover Kit	Belt Guard, Custom	Brake Reservoir, Custom	Cam Cover
Control Switches, Upgraded	Fender(s), Custom	Grips, Custom	Handlebars, Upgraded	Headlight, Custom
Horn, Custom	Kickstand, Custom	Mirrors, Custom	Paint, Custom	Primary Cover, Chrome Inner
Primary, Chrome Inner	Seat, Custom	Shock(s), Custom	Sprocket, Custom Belt	Suspension, Lowered
Swing Arm, Custom				

TIRES:	Pos.	Tread	Manufacturer	Dia.	Actual Size	Pos.	Tread	Manufacturer	Dia.	Actual Size
	Front	6/32	Dunlop	16"	16/80	Rear	6/32	Dunlop	16"	16/80

## EXCEPTION/DAMAGE: AN EXCEPTION IS A CONDITION NOTED OUT OF THE ORDINARY

Zone/Area/Qualifier	Type Description	Severity	Comments
<b>Exterior:</b>			
Center Fuel Tank/Cell	Chipped	Over 1 1/2 up to 2 in.	
Front Fender	Chipped	Over 1/2 up to 1 in.	
Center Frame	Gouged	Over 3 up to 4 in.	
Front Engine	Rust	Over 1 up to 1 1/2 in.	
Center Instrument Cluster	Inoperable	Unknown	ODDOMETER INOP TRUE MILES UNKNOWN
Rear Fender	Hardware Loose/Miss.	Missing	SEAT BOLT MISSING

## Tire &amp; Wheels:

Front Wheel	Gouged	Over 1/2 up to 1 in.
-------------	--------	----------------------

## Glass:

No Exceptions Recorded

## Inspection Comments:

STEERING HEAD IS RACKED AT 42 DEGREES. GAS TANK IS STRETCHED. PAINT ON FENDERS AND TANK IS MARBLEIZED.

